

---

**Van:** @sed.ethz.ch>  
**Verzonden:** vrijdag 15 februari 2019 12:11  
**Aan:**  
**CC:**  
**Onderwerp:** Re: Request for advice on an external reviewer of the Groningen seismic data

Hello

You mean, the instruments are given erroneous measurements, or wrong conversions are used, or wrong calibrations, so the PGA, PGV etc. are not correct ?

That would be a person knowing sensors, poles, zeros, etc. Which company provided the sensors? Nanometrics?

---

-----  
Prof.

Chair of Seismology and Director, Swiss Seismological Service  
ETH, NO H61, Sonneggstrasse 5, CH-8092 Zurich  
tel. + , fax  
@sed.ethz.ch; www.seismo.ethz.ch

---

**From:**  
**Date:** Friday, 15 February 2019 at 11:38  
**To:**  
**Cc:**  
**Subject:** Request for advice on an external reviewer of the Groningen seismic data

An issue has come up causing doubts on the quality of some of the seismic data recorded in the Groningen field. The present issue is with the accelerometers installed as part of the G-network since 2014. The issue has emerged as a result of work carried out under both the KEM02 and KEM04 research projects. SodM is concerned and considers that an independent external audit needs to be carried out at short notice on the seismic data recorded in the Groningen field. With initial focus on all the accelerometer data (including those recorded with the earlier B-network, and looking at all components).

Can you recommend someone who could carry out such an audit? It would need to be a top expert without connections to KNMI, NAM etc.

@ : any comments/additions?

Dr.

Senior Adviseur Toezichtsbeleid / Senior Advisor Regulatory Policies & Advice  
Staatstoezicht op de Mijnen / State Supervision of Mines  
Henri Faasdreef 312 | 2492 JP | The Hague P.O. Box 24037 | 2490 AA | Den Haag  
T + 31 M + 31 (0) / (0) F + 31 70  
[@minez.nl](mailto:@minez.nl) <http://www.sodm.nl>